







NOTICE TO MARINERS NO 05 of 2016

Our Ref: TM/PYD/ 56/95 Vol IX

25 January, 2016



Transport Malta

Malta Transport Centre Marsa, MRS 1917 Malta

Tel: (356) 2122 2203 Fax: (356) 2125 0365 Email: info.tm@transport.gov.mt

www.transport.gov.mt

Outer Munxar Tuna Farm SE Buoy - Missing

Reference is made to BA Chart 2538 – Malta (South East).

The Ports and Yachting Directorate, Transport Malta, notifies mariners that the South East Special Marker Light Buoy at Outer Munxar Tuna farm in position:

Latitude (N)

Longitude (E)

35° 52'.156

14º 40',600

Flashing quick 1 every 4 seconds is missing.

Chart Affected: BA Chart 2538, 194