







LOCAL NOTICE TO MARINERS No 135 of 2020

Our Ref: **TM/PYD/0001/20**

05 November 2020



Transport Malta

Malta Transport Centre Marsa, MRS 1917 Malta

Tel: (356) 2122 2203 Fax: (356) 2125 0365 Email: info.tm@transport.gov.mt

www.transport.gov.mt

Re-installation of floating pontoons in II-Maghluq, II-Port ta' Marsaxlokk

The Ports and Yachting Directorate, Transport Malta, notifies mariners that floating pontoons will be re-installed at II-Maghluq, II-Port ta' Marsaxlokk.

The preparation and re-installation of the floating pontoons will take place between Friday 6th November 2020 and Saturday 21st November 2020.

The assembling and re-installation of the pontoons will be carried out by scuba divers and will be accompanied by the support vessels "MV Gold Dredger", "MV Goldfinder" and "Anselma", and they will be displaying the international code of Signals flag "A".

Due to the re-installation, the area A, B, C, D and E (as shown hatched on attached chart) will be used as a working area, therefore this is a **restricted** area for the duration of the works.


POINT	LATITUDE (N)	LONGITUDE (E)	
Α	35°50.393	014°32'.769	Coast
В	35°50.398	014 <i>°</i> 32′.754	
С	35°50.427	014 <i>°</i> 32'.771	
D	35°50.395	014 <i>°</i> 32′.861	
Е	35°50.357	014 <i>°</i> 32′.839	Coast

Masters and operators of vessels are advised to keep a sharp lookout, navigate with caution and slow speed (no wake) when navigating close to the above indicated area.

They are to cooperate with the contractor on site and comply with any instructions given by Marsaxlokk Port Control (Marsaxlokk VTS) on VHF Channel 14.

Chart affected: BA 36

Positions referred to WGS 84 DATUM.



© Transport Malta all rights reserved

Whilst the Ports and Yachting Directorate, Transport Malta has endeavoured to ensure that the material supplied is suitable for the purpose described, it accepts no liability (to the maximum extent permitted by law) for any damage or loss of any nature arising from the use

The material supplied is used entirely at the Recipient's own risk.