



PORTS AND YACHTING DIRECTORATE

NOTICE TO MARINERS No 04 of 2026

Our Ref: **TM/PYD/ 56/95**

13 January 2026



Transport Malta

Malta Transport Centre,
Triq Pantar, Hal Lija, LJA 2021
Malta

Tel: (356) 2122 2203
Fax: (356) 2125 0365
Email: info.tm@transport.gov.mt

www.transport.gov.mt

Munxar East Cardinal Buoy – DESTROYED

Reference is made to BA Chart 36 – Marsaxlokk and Approaches.

The Ports and Yachting Directorate, Transport Malta, notifies mariners that the Outer Munxar East Cardinal Buoy flashing quick 3 every 10 seconds in position:

Latitude (N)

Longitude (E)

35° 50'.982

14° 35'.940

has been **DESTROYED**.

Mariners are advised to note the above and proceed with caution and slow speed when navigating in the area.

Chart Affected: **BA 36, 2538, 194**