





Merchant Shipping Directorate



## **WIRE ROPES MAINTENANCE**

**Information Notice 10** 

Notice to Shipowners, Ship Operators, Managers, Masters, Owners' Representatives and Recognised Organisations

The attention of the shipping community is drawn to the findings of a safety investigation into a maritime casualty involving the failure of a lifeboat wire ropes fall. The findings of the safety investigation highlight the possible factors for corrosion in wire ropes.

The Safety Investigation Report (Report No. 08/2012) may be accessed through the following

https://mti.gov.mt/en/Document%20Repository/MSIU%20Documents/Investigations%202013/ MV%20Celebrity%20Century\_Final%20Safety%20Investigation%20Report.pdf.

All concerned are strongly recommended to communicate the identified findings and lessons learnt from this safety investigation to their ships.

Merchant Shipping Directorate

23 April 2014

Malta Transport Centre Marsa, MRS 1917 Malta