





#### PORTS AND YACHTING DIRECTORATE

# **LOCAL NOTICE TO MARINERS No 045 OF 2021**

Our Ref: **TM/PYD 0001/21** 

03 May 2021



Malta Transport Centre, Triq Pantar, Ħal Lija, LJA 2021

Tel: (356) 2122 2203 Fax: (356) 2125 0365 Email: info.tm@transport.gov.mt

www.transport.gov.mt

Malta

## Repair works of the slipway and parts of two quays at II-Ponta tal-Qrejten

The Ports and Yachting Directorate, Transport Malta notifies mariners and the general public that repair work will be carried out on a slipway and on the quay next to the water polo pitch at II-Ponta tal-Qrejten in II-Port ta' Marsaxlokk.

The work will start on Thursday 13<sup>th</sup> May 2021 and is expected to be completed by Sunday 31<sup>st</sup> July 2021.

A silt curtain will be laid along the imaginary line joining points A, B, C and D for the repair of the slipway, whilst another silt curtain along the imaginary line joining V, W, X, Y and Z next to the water polo pitch will be laid, as shown on the attached chart.

A safety distance, of at least 10m from the silt curtains, shall be maintained at all times.


Some of the works will be carried out by scuba divers who will be displaying the International Code of Signals flag "A".

The indicated slipway with adjacent quay, as well as the quay forming part of the water polo pitch, shall not be used during this period due to the silt curtain.

Mariners and vessel operators are to navigate with caution and at slow speed (no wake) when in the vicinity. They are to co-operate with the contractor on site.

Mariners are to comply with instructions issued on VHF channel 14 and/or 16 by Marsaxlokk VTS.

Chart affected: BA 36



### © Transport Malta all rights reserved

#### DISCLAIMER

Whilst the Ports and Yachting Directorate, Transport Malta has endeavoured to ensure that the material supplied is suitable for the purpose described, it accepts no liability (to the maximum extent permitted by law) for any damage or loss of any nature arising from its use

The material supplied is used entirely at the Recipient's own risk.