

PORTS AND YACHTING DIRECTORATE

LOCAL NOTICE TO MARINERS No 102 of 2022

Our Ref: **TM/PYD 0001/22**

30 June 2022

Emergency Works at Marsascala North Breakwater, Marsascala

The Ports and Yachting Directorate, Transport Malta, notifies mariners and the general public that emergency repair works, are to be carried out, on the Marsascala north breakwater.

The works will start with immediate effect and are expected to be completed by the end of October 2022.

The works will be carried out from land with the assistance of divers, the International Code of Signals flag "A" will be displayed while diving operations are being carried out.

A silt curtain will be laid along the imaginary line joining points A, B, C D, E, F, and G as shown on the attached chart.

Owners of vessels that are moored or have a mooring within the area of 10 meters from the quay, are to remove such moorings and associated ground tackle with immediate effect.

Any vessels and moorings that are left in this area will be removed at the expense of the owner. No liability whatsoever will be accepted by the Authority for any damage that may be caused while removing the said vessels and moorings.

The quay cannot be used during this period due to the silt curtain.

Masters and vessel operators are to keep a sharp lookout and navigate at very slow speed (no wake) when in proximity of the above-mentioned area.

They are also to comply with any instructions given on VHF channel **12** and/or **16** by Valletta VTS

Chart affected: BA 36, 2538




Transport Malta

Malta Transport Centre Marsa, MRS 1917 Malta

Tel: (356) 2122 2203 Fax: (356) 2125 0365 Email: info.tm@transport.gov.mt

www.transport.gov.mt



© Transport Malta all rights reserved

DISCLAIMER

Whilst the Ports and Yachting Directorate, Transport Malta has endeavoured to ensure that the material supplied is suitable for the purpose described, it accepts no liability (to the maximum extent permitted by law) for any damage or loss of any nature arising from its use.

The material supplied is used entirely at the Recipient's own risk.