

PORTS AND YACHTING DIRECTORATE

LOCAL NOTICE TO MARINERS Nº 123 of 2023

Our Ref: TM/PYD/0001/23

13 July 2023



Transport Malta

Malta Transport Centre, Triq Pantar, Ħal Lija, LJA 2021 Malta

Tel: (356) 2122 2203 Fax: (356) 2125 0365 Email: info.tm@transport.gov.mt

www.transport.gov.mt

Fairway Established at Mgarr ix-Xini – Gozo

The Ports and Yachting Directorate, Transport Malta, notifies mariners and owners of vessels that a fairway has been established as indicated on the attached chart at Mgarr ix-Xini - Gozo.

The fairway is delineated by the points A, B, C, D, E and the coastline on the western side, as shown on the attached chart.

Points	Latitude (N)	Longitude (E)	Description	Flashing
Α	36° 01'.037	14° 16'.366	Lateral Starboard	Green
В	36° 01'.070	14° 16'.359	Lateral Starboard	Green
С	36° 01'.099	14° 16'.342	Lateral Starboard	Green
D	36° 01'.163	14° 16'.330	Lateral Starboard	Green
E	36° 01'.215	14° 16'.268	Coast	

The buoys will be seasonal (from May to September).


No vessels are permitted to anchor or moor within the fairway.

All moorings and ground tackle within the fairway are to be removed by their owner without delay in the interest of safety of navigation. Any moorings and ground tackle that are left in the fairway, will be removed at the expense of their owner. No liability whatsover will be accepted by the Authority for any damage that may be caused while removing the said vessels and moorings.

Furthermore, mariners are reminded that it is prohibited to lay any moorings and ground tackle without the prior permission of the Authority.

All positions are referred to WGS 84 DATUM.

Chart Affected: BA 211



© Transport Malta all rights reserved

DISCLAIMER

Whilst the Ports and Yachting Directorate, Transport Malta has endeavoured to ensure that the material supplied is suitable for the purpose described, it accepts no liability (to the maximum extent permitted by law) for any damage or loss of any nature arising from its use

The material supplied is used entirely at the Recipient's own risk.