



PORTS AND YACHTING DIRECTORATE

LOCAL NOTICE TO MARINERS N° 032 of 2026

Our Ref: **TM/PYD/0001/26**

11 March 2026



Transport Malta

Malta Transport Centre,
Triq Pantar, Hal Lija, LJA 2021
Malta

Tel: (356) 2122 2203
Fax: (356) 2125 0365
Email: info.tm@transport.gov.mt

www.transport.gov.mt

Repair works at Il- Fossa – Valletta (Marsamxett Harbour)

The Ports and Yachting Directorate, Transport Malta, notifies mariners and the general public that repair works on the road will be carried out at Il- Fossa, Valletta (Marsamxett Harbour).

The works will commence immediately and are expected to be completed by Sunday 21st June 2026.

A silt curtain will be laid along the line A, B, C and D, as shown on the attached chart.

Work will be conducted on the road from both the seaside and the boat chamber side. Scuba divers will display the International Code of Signals flag “A” during this time.

Any vessels or moorings left in the area, including the Il-Fossa boat chamber, will be removed at the owner's expense. The authority will not accept any liability for damage caused during the removal of these vessels.


Due to the above, passage in and out of the Il-Fossa boat chamber will be limited, and diving or swimming will be prohibited in the area for the duration of the work.

Mariners and owners of vessels are to proceed at very low speed (no wake) when navigating close to the area. They must keep at least 10m away from the silt curtain and cooperate with the on-site contractor.

All mariners are to comply with any instructions given on VHF Channel 12 and/or 16, by Valletta VTS and by any Enforcement Personnel on site.

Charts Affected: **BA 177**

Anchoring Prohibited



© Transport Malta all rights reserved

DISCLAIMER

Whilst the Ports and Yachting Directorate, Transport Malta has endeavoured to ensure that the material supplied is suitable for the purpose described, it accepts no liability (to the maximum extent permitted by law) for any damage or loss of any nature arising from its use.

The material supplied is used entirely at the Recipient's own risk.