



NOTICE TO MARINERS NO 07 of 2015

Our Ref: TM/PYD/ 56/95 Vol VII

24 February, 2015



Transport Malta

Malta Transport Centre Marsa, MRS 1917 Malta

Tel: (356) 2122 2203 Fax: (356) 2125 0365 Email: info.tm@transport.gov.mt

www.transport.gov.mt

Munxar East Cardinal Buoy - UNLIT

Reference is made to BA Chart 2538 – Malta (South East).

The Ports and Yachting Directorate, Transport Malta, notifies mariners that the East Cardinal Light Buoy at Outer Munxar reef in position:

Latitude (N) Longitude (E)

35° 50'.982 14° 35'.940

Is UNLIT.

Mariners are advised to note the above and proceed with caution and slow speed when navigating in the area.

Chart Affected: BA Chart 2538, 194