



PORTS AND YACHTING DIRECTORATE

## LOCAL NOTICE TO MARINERS No 015 OF 2019

Our Ref: **TM/PYD 0001/19**

22 February 2019



**Transport Malta**

Malta Transport Centre  
Marsa, MRS 1917  
Malta

Tel: (356) 2122 2203  
Fax: (356) 2125 0365  
Email: [info.tm@transport.gov.mt](mailto:info.tm@transport.gov.mt)

[www.transport.gov.mt](http://www.transport.gov.mt)

### **Repair works on Il-moll tal-Fekruna - Il-Bajja ta' San Pawl**

The Ports and Yachting Directorate, Transport Malta notifies mariners and the general public that repair works will be carried out on Il-moll tal-Fekruna – Il-Bajja ta' San Pawl.

The works will start on Wednesday 27<sup>th</sup> February 2019 within the area shown hatched on attached chart.

A diver may be involved in the works.

Due to weather limitations the work will be in progress until further notice.


Owners of vessels that are moored or have a mooring within the area are to remove such moorings and associated ground tackle as soon as possible. Any vessels and moorings that are left in this area will be removed at the expense of the owner. No liability whatsoever will be accepted by the Authority for any damage that may be caused while removing the said vessels and moorings.

Furthermore, mariners are reminded that it is prohibited to lay any moorings and ground tackle without the prior permission of the Authority.

Masters and vessel operators are instructed to keep a sharp lookout, navigate at very slow speed when approaching the area and that the quay cannot be used.

They are to comply with any instructions as given by Valletta Port Control (Valletta VTS) on VHF channel12.

Chart Affected: **BA 211A, 211B**



## Dahliet il-Fekrunda

© Transport Malta all rights reserved

### DISCLAIMER

Whilst the Ports and Yachting Directorate, Transport Malta has endeavoured to ensure that the material supplied is suitable for the purpose described, it accepts no liability (to the maximum extent permitted by law) for any damage or loss of any nature arising from its use.

The material supplied is used entirely at the Recipient's own risk.