







LOCAL NOTICE TO MARINERS No 044 of 2020

Our Ref: **TM/PYD/0001/20**

02 June 2020



Transport Malta

Malta Transport Centre Marsa, MRS 1917 Malta

Tel: (356) 2122 2203 Fax: (356) 2125 0365 Email: info.tm@transport.gov.mt

www.transport.gov.mt

Installation of floating pontoon infront of Macina in Id-Dahla tad-Dockyard, II-Port il-Kbir

The Ports and Yachting Directorate, Transport Malta, notifies mariners that floating pontoons will be installed at Id-Dahla tad-Dockyard in II-Port II-Kbir in front of II-Macina.

The preparation and installation of the floating pontoons will take place between Tuesday 9th June 2020 and Saturday 13th June 2020.

The vessels MV Gold Dredger and MV Goldfinder will be used for the assembling and installation of the pontoons.


Due to the installation, the area A, B, C and D (as shown hatched in red on attached chart) will be used as a working area, therefore this is a **restricted** area for the duration of the works.

POINT	LATITUDE (N)	LONGITUDE (E)	
Α	35°53'.146	014°31'.207	Coast
В	35°53'.147	014°31'.216	
С	35°53'.107	014°31'.226	
D	35°53'.104	014 <i>°</i> 31′.203	Coast

Masters and operators of vessels are advised to keep a sharp lookout, navigate with caution and slow speed (no wake) when navigating close to the above indicated area. They are to cooperate with the contractor on site and comply with any instructions given by Valletta Port Control (Valletta VTS) on VHF Channel 12.

Chart affected: **BA 177**

Positions referred to WGS 84 DATUM.



© British Crown Copyright 1970, 1983, 1986, 1988, 1999, 2000 All rights reserved.

The UK Hydrographic Office makes the accompanying data Available to Malta Maritime Authority (Transport Malta) Under the terms and conditions of agreement HO 1427/020930/01.

DISCLAIMER

Whilst the UK Hydrographic Office has endeavoured to ensure That the material supplied is suitable for the purpose described, It accepts no liability (to the maximum extent permitted by law) For any damage or loss of any nature arising from its use. The material supplied is used entirely at the Recipient's own risk.