

PORTS AND YACHTING DIRECTORATE

NOTICE TO MARINERS No 59 of 2020

Our Ref: TM/PYD/ 299/81

22 December 2020

Chart Correction - New Breakwater at II-Qrejten in II-Port ta' Marsaxlokk

Reference is made to BA Charts 36 – Marsaxlokk

The Ports and Yachting Directorate, Transport Malta notifies Mariners that a new breakwater has been established at II-Qrejten in II-Port ta' Marsaxlokk.

The breakwater is formed by joining the following positions and the intermediate coastline as shown on attached chart:

	Latitude (N)	Longitude (E)	
from	35° 50'.139	014º 32'.745	Coast
to	35° 50'.155	014º 32'.790	
to	35º 50'.157	014º 32'.788	
to	35° 50'.159	014º 32'.792	
to	35° 50'.153	014º 32'.796	
to	35° 50'.136	014º 32'.746	Coast

Furthermore, a light has been established at the end of the breakwater in the following position

	Latitude (N) 35º 50'.153		Longitude (E) 014º 32'.794
The characteristics of the I	ight are:	FI(2).F	8.5s 11m 7M
Positions referred to:	WGS 84 DA ⁻	TUM	

Charts Affected: BA Chart 36

tm

Transport Malta


Malta Transport Centre, Triq Pantar, Hal Lija, LJA 2021 Malta

 Tel:
 (356) 2122 2203

 Fax:
 (356) 2125 0365

 Email:
 info.tm@transport.gov.mt

www.transport.gov.mt



 $\ensuremath{\mathbb{C}}$ $\ensuremath{\,$ British Crown Copyright 1970, 1983, 1986, 1988, 1999, 2000 All rights reserved.

The UK Hydrographic Office makes the accompanying data Available to Malta Maritime Authority (Transport Malta) Under the terms and conditions of agreement HO 1427/020930/01.

DISCLAIMER

Whilst the UK Hydrographic Office has endeavoured to ensure That the material supplied is suitable for the purpose described, It accepts no liability (to the maximum extent permitted by law) For any damage or loss of any nature arising from its use. The material supplied is used entirely at the Recipient's own risk.